

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

APPLICANT : Nobuaki KIYA Confirmation No. 6906  
SERIAL NO. : 10/590,235  
FILED : August 22, 2006  
FOR : METHOD OF DETECTING AND RESPONDING TO A  
COOLING SYSTEM FAILURE IN A POWER SUPPLY DEVICE  
(as amended)  
PATENT NO. : **7,771,864 B2** Issued 10 August 2010

**CERTIFICATE OF CORRECTION BRANCH**  
COMMISSIONER FOR PATENTS  
P. O. Box 1450  
Alexandria, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**PURSUANT TO 37 C.F.R. §1.323**

SIR:

It is respectfully requested that the enclosed certificate of correction be issued for the above Patent under authority of 35 USC § 355.

The changes represent correction of minor errors which were not previously discovered.

The fee under 37 C.F.R. 1.20(a) in the amount of \$100.00 is being paid by credit card. If a petition is required to correct these errors, please consider this such a petition and charge the fee in the amount of \$130.00 to Deposit Account No. 11-0600.

Respectfully submitted,

Dated: 23 December 2010

/Shawn W. O'Dowd/

Shawn W. O'Dowd  
(Reg. No. 34,687)

KENYON & KENYON LLP  
1500 K Street, N.W., Suite 700  
Washington, DC 20005  
Tel: (202) 220-4200  
Fax: (202) 220-4201

UNITED STATES PATENT AND TRADEMARK OFFICE

**CERTIFICATE OF CORRECTION**

**PATENT NO.** : 7,771,864 B2 Page 1 of 1  
**DATED** : 10 August 2010  
**FILED** : 22 August 2006  
**INVENTOR(S)** : Nobuaki KIYA, et al

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>Column</u>	<u>Line</u>	
16	55	Before "according" delete "a".
17	16	After "cooling system" delete "is set".

**MAILING ADDRESS OF SENDER:**

Shawn W. O'Dowd  
KENYON & KENYON LLP  
1500 K Street, N.W., Suite 700  
Washington, DC 20005

Patent No.: 7,771,864 B2